




PUMP ASSEMBLY WITH ONE PIECE PISTON  
Donald J. Shanklin et al.  
Appl. No.: 10/790,666 Atty Docket: HAYESPR.1CP3C4

Fig. 1



PUMP ASSEMBLY WITH ONE PIECE PISTON  
Donald J. Shanklin et al.  
Appl. No.: 10/790,666 Atty Docket: HAYESPR.1CP3C4




Fig. 1a




Fig. 1b


Fig. 1c

PUMP ASSEMBLY WITH ONE PIECE PISTON


Donald J. Shanklin et al.

Appl. No.: 10/790,666 Atty Docket: HAYESPR.1CP3C4

*Fig. 1d*




*Fig. 1e*




PUMP ASSEMBLY WITH ONE PIECE PISTON  
Donald J. Shanklin et al.  
Appl. No.: 10/790,666 Atty Docket: HAYESPR.1CP3C4

*Fig. 2*




PUMP ASSEMBLY WITH ONE PIECE PISTON  
Donald J. Shanklin et al.  
Appl. No.: 10/790,666 Atty Docket: HAYESPR.1CP3C4


*Fig. 3*



*Fig. 4*



PUMP ASSEMBLY WITH ONE PIECE PISTON  
Donald J. Shanklin et al.  
Appl. No.: 10/790,666 Atty Docket: HAYESPR.1CP3C4



PUMP ASSEMBLY WITH ONE PIECE PISTON  
Donald J. Shanklin et al.  
Appl. No.: 10/790,666 Atty Docket: HAYESPR.1CP3C4

Fig. 6







Fig. 6a




*Fig. 2*




*Fig. 8*




PUMP ASSEMBLY WITH ONE PIECE PISTON  
Donald J. Shanklin et al.  
Appl. No.: 10/790,666 Atty Docket: HAYESPR.1CP3C4




*Fig. 9a*



*Fig. 9*



*Fig. 10*






*Fig. 9b*

PUMP ASSEMBLY WITH ONE PIECE PISTON


Donald J. Shanklin et al.

Appl. No.: 10/790,666 Atty Docket: HAYESPR.1CP3C4




PUMP ASSEMBLY WITH ONE PIECE PISTON  
Donald J. Shanklin et al.  
Appl. No.: 10/790,666 Atty Docket: HAYESPR.1CP3C4


*Fig. 12*  
(PRIOR ART)



*Fig. 13*  
(PRIOR ART)



*Fig. 14*  
(PRIOR ART)



PUMP ASSEMBLY WITH ONE PIECE PISTON

Donald J. Shanklin et al.

Appl. No.: 10/790,666 Atty Docket: HAYESPR.1CP3C4





Fig. 16

Fig. 15

PUMP ASSEMBLY WITH ONE PIECE PISTON  
Donald J. Shanklin et al.  
Appl. No.: 10/790,666 Atty Docket: HAYESPR.1CP3C4





Fig. 17

PUMP ASSEMBLY WITH ONE PIECE PISTON


Donald J. Shanklin et al.

Appl. No.: 10/790,666 Atty Docket: HAYESPR.1CP3C4

*Fig. 18*



*Fig. 19*



PUMP ASSEMBLY WITH ONE PIECE PISTON

Donald J. Shanklin et al.

Appl. No.: 10/790,666 Atty Docket: HAYESPR.1CP3C4

Fig. 20






Fig. 21




PUMP ASSEMBLY WITH ONE PIECE PISTON  
Donald J. Shanklin et al.  
Appl. No.: 10/790,666 Atty Docket: HAYESPR.1CP3C4

*Fig. 22*




*Fig. 23*




PUMP ASSEMBLY WITH ONE PIECE PISTON  
Donald J. Shanklin et al.  
Appl. No.: 10/790,666 Atty Docket: HAYESPR.1CP3C4


*Fig. 24*



*Fig. 25*




*Fig. 25a*




PUMP ASSEMBLY WITH ONE PIECE PISTON  
Donald J. Shanklin et al.  
Appl. No.: 10/790,666 Atty Docket: HAYESPR.1CP3C4

*Fig. 26*



*Fig. 27*



**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS**
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- FADED TEXT OR DRAWING**
- BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- SKEWED/SLANTED IMAGES**
- COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- GRAY SCALE DOCUMENTS**
- LINES OR MARKS ON ORIGINAL DOCUMENT**
- REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- OTHER: \_\_\_\_\_**

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**